

PRIORITY

GROUP 1
Excluded from automatic
downgrading and
declassification

SECRET

FIVE DEGREE ANGLE AND ARE LOCATED EIGHT INCHES FROM THE TAKE-UP END OF MOST FRAMES. BANDING IS NOTICEABLE ON SOME FRAMES. IMAGE DEGRADATION FROM THE ABOVE ANOMALIES IS MINOR.

D. PHYSICAL DEGRADATIONS: FINE EMULSION SCRATCHES ARE PRESENT THROUGHOUT. THREE HEAT AND TWO ULTRASONIC SPLICES ARE PRESENT IN THE MATERIAL.

E. DATA RECORDING EQUIPMENT: DATA RECORDING EQUIPMENT FUNCTIONED PROPERLY. WRITE-UP CARD IS DIFFICULT TO READ DUE TO HEAVY EXPOSURE.

F. OTHER: LAST TITLED FRAME IS 1305; COUNTER 1305. 4. POSITIVES: FAIR. MANY OF THE HIGHLIGHT AREAS, O.N. D-MAX, ARE WASHED OUT, INDICATING SOME OF THE POSITIVES WERE SLIGHTLY UNDEREXPOSED.

GP-1

S E C R E T

END OF MESSAGE